



INSTRUCTIONS FOR USING AND SETTING THE TELADROP NON-RESETTABLE IMPACT INDICATOR

Each *TelaDrop* is provided with a carton warning label and a bill of lading label to be used as a system for monitoring your product during transit. We suggest the bill of lading label be placed on the bill of lading to notify the carrier or consignee that the shipment contains an impact monitor. The carton warning label should be placed on the top or side of the package. The *TelaDrop* may be placed on the inside or the outside of the package or on the product.

MOUNTING

Mount the *TelaDrop* with either adhesive back tape or two No. 6-32 screws. There is pressure-sensitive tape on the back of the indicator. Remove the liner from the tape and press the unit to a flat surface on the package or on the product to be monitored. The *TelaDrop* impact indicator must be aligned with the arrows pointed toward the direction of shock to be monitored. Three units are needed to provide complete three-dimensional readout (six directions).

TO ACTIVATE THE NON-RESETTABLE TELADROP

Pull the metal pin on the top of the *TelaDrop*. It cannot be reset. Therefore, care must be exercised not to trip the device as the pin is being pulled.