INSTRUCTIONS FOR USING AND SETTING
THE TELA*DROP* RESETTABLE IMPACT INDICATOR

Each Tela*Drop* is provided with a carton warning label and a bill of lading label to be used as a system for monitoring your product during transit. We suggest the bill of lading label be placed on the bill of lading to notify the carrier or consignee that the shipment contains an impact monitor. The warning label should be placed on the top or side of the package. The Tela*Drop* may be placed on the inside or the outside of the package or on the product.

MOUNTING

Mount the Tela*Drop* with either adhesive back tape or two No. 6-32 screws. There is pressure-sensitive tape on the back of the indicator. Remove the liner from the tape and press the unit to a flat surface on the package or on the product to be monitored. The Tela*Drop* impact indicator must be aligned with the arrows pointed toward the direction of shock to be monitored. Three units are needed to provide complete three-dimensional readout (six directions).

TO ACTIVATE THE RESETTABLE TELA*DROP*

A small 1/16-inch hole is provided in the center of each end of the plastic housing for the purpose of activating and resetting the unit. This hole is on the side of the case. A small paper clip with one end bent out can be used for activating and resetting the unit. Push the wire end of the paper clip into the small hole until the arrow snaps back into hiding and the spring is reset. Apply only enough force to reset the arrow and spring assembly. The arrow will snap quickly into a covered position and a slight snap can be heard. The impact indicator is now ready to use.

CALL TOLL FREE HOTLINE 1-800-321-5160   www.telatemp.com
Telatemp Corporation   2910-C East La Palma Avenue   Anaheim,CA USA 92806-2618
Phone +714-414-0343   Fax +714-414-0383   customerservice@telatemp.com